



MIT508 - Sound issue.

Factory RCA port with nothing connected to it causes the two ports to be in MONO mode which will cause GROM to not play properly for sound reproduction. A remedy to the issue is to have something plugged into one of side of the factory Auxiliary RCA input. This will trigger the RCA inputs back to Stereo signal allowing GROM to reproduce sound properly to the stereo AUX mode.



1. Locate RCA cable scrape or one you do not care about and cut wire off end of it. We will only use the RCA connector end of it.



2. Plug the RCA connector into the RED side o the factory Auxiliary port



3. Leave it connected at all times with no wires connected to it and this should resolve poor sound issue with GROM audio playback.